


# Mismatched Coil Testing to Simulate Condenser Replacement



## **13 SEER HP Rating with Proper 13 SEER Indoor Coil**

<b>Capacity (BTU/hr)</b>	<b>36794</b>
<b>SEER</b>	<b>13.62</b>
<b>Superheat (service valve) (F)</b>	<b>17.93</b>
<b>Subcool (service valve) (F)</b>	<b>6.08</b>
<b>Liquid press (psig)</b>	<b>222.76</b>
<b>Return gas press (psig)</b>	<b>81.38</b>

# Tested with 10 SEER ID Coil and 13 SEER HP

**Cooling** 95 F Outside / 80 F Inside  
Factory Refrigerant Charge: 8 lb 7 oz

	Rated	Tested
<b>Capacity too low</b> Capacity (BTU/hr)	36794	22208
<b>SEER too low</b> SEER	13.62	8.46
Superheat (service valve) (F)	17.93	54.54
Subcool (service valve) (F)	6.08	0.98
<b>Charge appears too low</b> Liquid press (psig)	222.76	209.94
Return gas press (psig)	81.38	58.42

# Tested with 10 SEER ID Coil and 13 SEER HP

**Heating** 47 F Outside / 70 F Inside  
Factory Refrigerant Charge: 8 lb 7 oz

	Rated	Tested
<b>Capacity too low</b> Capacity (BTU/hr)	36484	29997
<b>EER too low</b> EER	15.71	10.60
Superheat (service valve) (F)	12.05	11.24
Subcool (service valve) (F)	21.07	26.73
<b>Charge appears OK</b> Liquid press (psig)	203.88	233.03
Return gas press (psig)	58.09	60.86

# Tested with 10 SEER ID Coil and 13 SEER HP

Cooling 95 F Outside / 80 F Inside

Refrigerant Charge: 14 lb 14 oz

	Rated	Tested
<b>Capacity too low</b> Capacity (BTU/hr)	36794	29823
<b>SEER too low</b> SEER	13.62	8.92
Superheat (service valve) (F)	17.93	14.68
Subcool (service valve) (F)	6.06	17.58
<b>Charge appears OK</b> Liquid press (psig)	222.76	262.49
Return gas press (psig)	81.38	79.96

# Tested with 10 SEER ID Coil and 13 SEER HP

**Heating** 47 F Outside / 70 F Inside  
Refrigerant Charge: 14 lb 14 oz

	Rated	Tested
<b>Capacity too low</b> Capacity (BTU/hr)	36484	18706
<b>EER too low</b> EER	15.71	5.74
Superheat (service valve) (F)	12.05	6.6
<b>Subcool high</b> Subcool (service valve) (F)	21.07	87.00
<b>HPS opened at 410 psi</b> Liquid press (psig)	203.88	410.1
Return gas press (psig)	58.09	64.60

# Tested with 10 SEER ID Coil and 13 SEER HP

**Cooling** 95 F Outside / 80 F Inside

Refrigerant Charge: 10 lb 0.5 oz

	Rated	Tested
<b>Capacity too low</b> Capacity (BTU/hr)	36794	26188
<b>SEER too low</b> SEER	13.62	9.08
Superheat (service valve) (F)	17.93	50.31
Subcool (service valve) (F)	6.08	4.12
Liquid press (psig)	222.76	214.25
<b>Charge appears low</b> Return gas press (psig)	81.38	62.48



# Tested with 10 SEER ID Coil and 13 SEER HP

**Heating** 47 F Outside / 70 F Inside

Refrigerant Charge: 10 lb 0.5 oz

	Rated	Tested
<b>Capacity too low</b> Capacity (BTU/hr)	36484	30178
<b>EER too low</b> EER	15.71	9.47
Superheat (service valve) (F) <small>77.06</small>	12.05	11.22
Subcool (service valve) (F)	21.07	62.23
<b>Discharge press high</b> Liquid press (psig)	203.88	310.50
Return gas press (psig)	58.09	61.83



# Tested with 10 SEER ID Coil and 13 SEER HP

**Cooling** 95 F Outside / 80 F Inside

Refrigerant Charge: 10 lb 6 oz with **TXV**

	Rated	Tested
<b>Capacity too low</b> Capacity (BTU/hr)	36794	31266
<b>SEER too low</b> SEER	13.62	11.85
Superheat (service valve) (F)	17.93	26.22
Subcool (service valve) (F)	6.08	2.20
Liquid press (psig)	222.76	220.06
<b>Charge appears low</b> Return gas press (psig)	81.38	77.06

## Tested with 10 SEER ID Coil and 13 SEER HP

**Heating** 47 F Outside / 70 F Inside

Refrigerant Charge: 10 lb 6 oz with **TXV**

	Rated	Tested
Capacity (BTU/hr)	36484	

**High Pressure Switch opened because head pressure exceeded 410 psi.  
Charge needs to be reduced for heating but cooling is requiring more charge**

Liquid press (psig)	203.88	
Return gas press (psig)	58.09	

# **Result of Only Replacing Condensing Unit**

- Up to 40% reduced capacity in cooling meaning system may not be able to keep up with thermostat setting.
- Up to 48% reduced capacity in heating resulting in strip heat coming on earlier.
- Up to 40% reduced efficiency in cooling resulting in higher power bills. Not only is it going to run longer but dollars per cooling will be more as well.
- Up to 60% reduced efficiency in heating resulting in higher power bills.
- System charging becomes critical since the charge might seem correct for one condition but flood on another.
- TXV will not solve the charge problem for all cases since the SH and SC can change dramatically with condition.
- All of these situations will result in numerous service calls and most likely the only way to resolve it is to replace the indoor coil with a larger coil anyway.