

Applies To: **1999-02 Odyssey** – ALL without Navigation System
1998-02 Accord – ALL

February 12, 2002

Clock Light Does Not Work

(Supersedes 01-097, dated November 6, 2001)

PROBLEM

The clock does not light up with the other instrument panel lights.

CORRECTIVE ACTION

Replace the clock illumination bulb.

PARTS INFORMATION

■ Clock Bulb: P/N 35505-S84-B02, H/C 5435540

WARRANTY CLAIM INFORMATION

In warranty: The normal warranty applies.

Operation Number: 715106

Flat Rate Time: 0.3 hour for Odyssey
0.2 hour for Accord

Failed Part: P/N 35505-S84-N01
H/C 5435557

Defect Code: 032

Contention Code: B01


Template ID: 01-097A for Odyssey
01-097B for Accord

Skill Level: Repair Technician

Out of warranty: Any repair performed after warranty expiration may be eligible for goodwill consideration by the District Service Manager or your Zone Office. You must request consideration, and get a decision, before starting work.

REPAIR PROCEDURE

1. *Odyssey:* Remove the instrument panel (see page 20-68 in the service manual). *Accord:* Remove the clock from the center panel (see page 22-129 in the service manual).
2. Replace the clock illumination bulb.



3. Reinstall the clock or the instrument panel.
4. Set the clock.