



getting fuel from tank. will run as long as gas is squirted in carb. when top of carb is removed, there is no fuel in bowl. tried another carb from another mower. it operates the same as the original, which tells me it is not in the carb itself but in the fuel delivery system somewhere. i believe that whatever makes the fuel pump operate has failed. what is this hose here for? is it a vacuum line? does vacuum cause the fuel pump to work? where does the vacuum originate from? could that be what is damaged? what procedures are required to repair this vacuum problem?