


DANGER: ELECTRICAL SHOCK HAZARD - DISCONNECT
CONNECTION WIRING DIAGRAM

USE COPPER CONDUCTORS ONLY
 208/230V 60HZ 1PH



COLOR CODE		LINE CODE		
BLACK....BK	ORANGE....O	LINE VOLTAGE FACTORY	TRANS....TRANSFORMER	
BLUE....BL	RED.....R	LINE VOLTAGE FIELD	COMPR....COMPRESSOR	
BROWN...BR	VIOLET....V	LOW VOLTAGE FACTORY	CAP.....CAPACITOR	
GRAY....CY	WHITE....W	LOW VOLTAGE FIELD	CONT.....CONTACTOR	
GREEN...G	YELLOW...Y		LVTB...LO VOLT TERM BRD	