Replacing a Saddle Valve with the Add-A-Line Full-Slip Valve Tee



- Perfect for adding ice makers, humidifiers, hot water taps, or filtered water taps
- Easy to install
- Quality brass valve replaces cheap saddle valve that leaks and clogs
- See enclosed brochure for additional valve options.



	Turn off house water. With a permanent marker, mark the tube at the outside and inside of each brass compression fitting of the Add-A-Line.	2 Cut	Turn off house water. Cut out a one inch section of copper tube, including the piercing valve. Cut the flexible line to the ice maker or humidifier. Be sure to leave enough line to reach the new Add-A-Line.
3	Slide a compression nut and a brass ferrule over each section of cut tube. Then, slip the Add-A-Line over one section of tube, then the other, lining up the compression threads with the outer marks.	4 Hold	With two wrenches, tighten each compression nut. Take care not to over tighten.
5 Hold	Slide the top compression nut and the brass ferrule (for copper tube) or the plastic ferrule (for poly tube) over the line to the appliance. Tighten the compression nut onto the Add-A-Line.		Turn on house water. Check for leaks.





Add-A-Line[™] Clamshell Packaging in Display Boxes





Item No.	Trunk	Ball Valve Tee	Min. Qty.	Case Qty.	List Price			
BAR-CODED CLAMSHELLS IN A CUT CASE BOX								
601-20CV	5%" O.D. compression full-slip	1/4" O.D. compression	6	6	27.29 ea			
601-30CV	⁷ ⁄⁄⁄⁄⁄⁄⁄⁄⁄⁄⁄⁄⁄⁄8" O.D. compression full-slip	1/4" O.D. compression	6	6	33.99 ea			
601-21CV	5%" O.D. compression full-slip	3/8" O.D. compression	6	6	25.24 ea			
601-31CV	⁷ ⁄⁄⁄⁄⁄⁄⁄⁄⁄⁄⁄⁄⁄⁄8" O.D. compression full-slip	3/8" O.D. compression	6	6	34.32 EA			
601-22CVM	5/8" O.D. compression full-slip	1/2" FSWT/MIP thread	6	6	26.10 EA			
601-32CVM	⁷ ⁄⁄⁄⁄⁄⁄⁄⁄⁄⁄⁄⁄⁄⁄⁄8" O.D. compression full-slip	1/2" FSWT/MIP thread	6	6	34.92 ea			
601-22CVX	5/8" O.D. compression full-slip	½" PEX barb	6	6	25.25 ea			
601-32CVX	⁷ ⁄⁄₃" O.D. compression full-slip	½" PEX barb	6	6	34.79 ea			
601-20V	1⁄2" female sweat full-slip	1/4" O.D. compression	6	6	20.33 EA			
601-30V	³ ⁄ ₄ " female sweat full-slip	1/4" O.D. compression	6	6	21.04 EA			
601-21V	1⁄2" female sweat full-slip	3/8" O.D. compression	6	6	18.30 EA			
601-31V	³ ⁄ ₄ " female sweat full-slip	3/8" O.D. compression	6	6	19.41 ea			
601-22VM	1/2" female sweat full-slip	1/2" FSWT/MIP thread	6	6	19.16 EA			
601-32VM	³ ⁄4" female sweat full-slip	1/2" FSWT/MIP thread	6	6	20.18 EA			
601-22VX	1/2" female sweat full-slip	1/2" PEX barb	6	6	18.08 EA			
601-32VX	³ ⁄4" female sweat full-slip	1/2" PEX barb	6	6	19.18 ea			

DISTRIBUTED BY

tel: 1-800-821-3944 fax: 1-800-758-5950 www.siouxchief.com P.O. Box 397 24110 South Peculiar Drive Peculiar, Missouri 64078 U.S.A.

